



BOTTOM

CORE TOP

CORE BOTTOM

DoctorMobile.org



- 50_TRX_ANT2_LB_LMB_MB_HB_L1
- 50_TRX_TPLX_ANT_LB_LMB_MB_HB_L1
- 50_TRX_HBDSM_HB_ANT1
- 50_TRX_LBDSM_ANT1
- 50_RX_XCVR_DRX6_LB_DSM_RXOUT1
- 50_TX_IN_XCVR_TX1_HB1
- 50_RX_XCVR_DRX2_HB_DSM_RXOUT_DRX1
- 50_TRX_LMB_HB_PORTB_TX_M
- 50_TRX_LMB_HB_PORTB_RX1_M
- 50_TRX_HB_PAD_ANT1
- 50_TRX_LB_PAD_ANT1
- 50_TRX_CPLR_L_CPL1_IN_LB_LMB_MB_HB
- 50_TRX_ANT1_LB_LMB_MB_HB
- 50_TX_IN_XCVR_TX0_HB1
- 50_TRX_IN_LMB_PAD_2G_MB_OUT_M
- 50_RX_XCVR_PRX2_LMB_MBT_HBT_PRX_OUT
- 50_TRX_IN_LMB_PAD_2G_LB_OUT_M
- 50_TX_IN_XCVR_TX1_LB_JB
- 50_TX_IN_XCVR_TX0_LB2G



DoctorMobile.org
+989101967177